

Resolved on: 10/2/89
 By: L.W. Epley EZO/B14
 Inspector C P O

These code violations have not been corrected. Please follow with legal action.

**RESOLVED
HOLD IN INACTIVE FILE**

Citation: WA 2917
 Court Date: 9-6-89
 File Resolved on: 79
 By: _____
 Inspector: _____

NUMBER OF REINSPECTIONS 2

Company Officer _____ Date _____

Inspector _____

COMPANY REINSPECTION

September 6, 1989

F.M.O. REINSPECTION

Pier 91 - Building 19
 1515 West Garfield
 Pacific Northern Oil
 20-288:171-9 (284-2911)

RCRA PERMIT
 ADMINISTRATIVE RECORD
 ITEM NUMBER _____
 TOTAL NUMBER OF PAGES _____

K/J/C

JUL 1 1992

RECEIVED

FILE COPY

Mr. George Markwood, Manager
 100 W. Harrison St. - Suite 200
 Seattle, WA 98117

Dear Mr. Markwood:

A fire inspection of the above-named premises disclosed violations of City Ordinance which must be corrected as follows:

1. Remove accumulations of oil residue from the main cargo pump room located on the southwest wall and floor. Future accumulations shall be removed as they occur. (SFC 79.112)

2. To the pipe alley:

Remove all accumulations of oil in the bermed area of the waterways. Future accumulations shall be removed on a regular basis as they occur. (SFC 79.111)

3. Confine the combustible waste/storage to covered metal containers as follows:

Throughout the top of the bulk storage tanks at the level testing port:

Remove the oily rags from this area and dispose of or store in a container approved for that purpose. (SFC 11.201(b))

4. City Ordinance requires that permits be obtained from the Chief of the Fire Department to store, use, or maintain hazardous materials or processes. In this regard, you apparently require permit(s) as follows:

For cutting and welding, three units or less.
 (ORD. 111001, Schedule "A" -- SFC 4.101)

Upon receipt of the attached application(s) in this office, a Fire Prevention Inspector will contact you.

USEPA RCRA



3012553

A Fire Safety Inspector will re-check these items for completion in approximately 15 days. If you have questions call 386-1450

SEP 27

Resolved on: _____

Citation No. _____

By: _____
Inspector C / P / OThese code violations have not been
corrected. Please follow with legal action.

Court Date: _____

NUMBER OF
REINSPECTIONS _____

File Resolved on: _____

By _____
Inspector

Company Officer Date

1515 West Garfield

COMPANY
REINSPECTIONPacific Northern Oil
20-288:171-9 (284-2911)
Page 2F.M.O.
REINSPECTION5. Regarding the liquid spill that occurred on August 22, 1988 at the
northwest end of the facility, outside:In the event of an accidental release of a hazardous material, the owner
or occupant shall immediately report such incident to the Fire
Department. (SFC 11.301)

Fire safety indicates these items must be corrected as soon as possible.

Very truly yours,

CLAUDE HARRIS,
Chief of Fire DepartmentBy
B.L. Hansen,
Fire Marshal

BLH:dp

Enclosure

cc: Mr. Nate Mathews
Plant Manager, CHEMPRO
5501 Airport Way-S.
Seattle, WA 98108A Fire Safety Inspector will re-check these items for completion in
approximately 15 days. If you have questions call 386-1450